

STRAPPING AS SUPPLIED
FOR EXPORT OR "NO
CHARACTER" UNIT

TYPE "S" UNIT

Demon 1039

over 40

TYPE "T" UNIT

FR-1 MATH

GAS sh.

Supex


25-40

TYPE "X" (P-P) UNIT

6MT

220


MITCHELL A. CUTLER MK II



A
B
C
D

6-20-79

TYPE "L"



Terminals (designated by "O") are to be wired as formatted above to achieve the desired transformer characteristics for ultimate use. If there are any difficulties, contact Mitchell A. Cutler Co.

(O) This designation indicates INPUT JACKS for strapping orientation.

PLEASE NOTE: When strapping is accomplished, please be sure to indicate on the blue stick-on patch, next to the serial number, the type of strapping that was done.